





3




4



5

Attach 11-beam  
to back of motors




6



7



8



9



10




11



12



13



14






15




16





17




18



19



20



21



Attach motors in  
ports A and B